

CITY HALL IMPROVEMENTS

1/4/2017



New insulated ductwork installed in shaft.



Three new boilers ready for installation.



Deteriorated pipe in shaft.



Existing pipe showing mineral build-up.